




2017 Aquafix Case Study – Defuniak Springs, FL
Aquafix Product Used: AquaSticker
Mike Smith, Field Manager

Project Overview:

This case study focuses on one of our accounts serviced out of our Navarre office, located in the Florida Panhandle. A portion of this 38-acre lake was covered with milfoil, bladderwort, slender spikerush, plus water shield and fragrant water lilies. In order to effectively treat the lake, we applied a combination of **AquaSticker** mixed with clipper, diquat, argos, and copper to clear the undesirable growth and impact major results. The south end of the lake was extremely difficult to access due to heavy amounts of tree stumps in the water column; however we were able to utilize several pieces of equipment to cover around 60% to 70% of it during treatment.

Results:

During final inspection, which was approximately 40 days later, the lake looked pristine. We couldn't have been happier with the results. Although just a percentage of the lake was treated, the products we applied restored the lake back to its natural beauty.





The Lake Doctors, Inc.
Aquatic Management Services[®]



Figure 1 - BOAT RAMP LOOKING SOUTH BEFORE



Figure 2 - BOAT RAMP LOOKING SOUTH AFTER



The Lake Doctors, Inc.
Aquatic Management Services[®]



Figure 3 – VIEW FROM WEST SIDE BEFORE



Figure 4 – VIEW FROM WEST SIDE AFTER